



STRATEGIC
Site™

Powered by Geospatial Analytics

AI Powered Assessments with Quick Verification Agent™

Asset Assessment – Dallas, TX Facility

Progress: 6 of 13 Complete

▶ **Asset Class: HVAC**

▶ AHU-01 | Air Handling Unit | 15,000 CFM

▼ RTU-01 | Rooftop Unit | 20 Ton

Filters

- ☒ Clean / Replaced
- ☐ Dirty
- ☐ Needs Replacement

Air Vents

- ☒ Clear
- ☐ Partially Blocked
- ☐ Obstructed

Coil Condition

- ☐ Clean
- ☒ Some Debris
- ☐ Heavy Debris

Verify Answers **Edit Answers**

Step 1: Select Asset

Step 2: Review Data

Step 3: Verify Results

The #1 Intelligent Assessment

Knows Your Assets Instantly

Asks Only What Matters

Understands History & Context

Delivers Results in Seconds

COMPLETE COMPLIANCE INSPECTIONS IN SECONDS. ONE, TWO, THREE, DONE!

HOW MANY INSPECTIONS
DO YOU TAKE A YEAR?


10,000

25,000

100,000

Inspection Types

Pen & Paper




2,000
hours

5,000
hours

10,000
hours

Spreadsheets




1,500
hours

3,750
hours

7,500
hours

eForms



1,000
hours

2,500
hours

5,000
hours

ANNUAL HOURS SAVED

Your Results. Ready When You Are.

Automatically calculated, ***instantly*** displayed ***without***
the ***paperwork*** or ***wait time***.